

Tech Info Library

CLW 12/600 PS: Windows 95 Problems w/ vecpd.386 (2/97)

Article Created: 11 December 1995
Article Reviewed/Updated: 27 February 1997
TOPIC
I have installed Windows 95 on my PC-compatible, and I am having some trouble printing to the Color LaserWriter 12/600 PS printer. I was able to print using Windows 3.11.
DISCUSSION
The Color LaserWriter 12/600 PS printer software for Windows 3.1x installs VECPD.386, a bidirectional parallel port driver that was not intended for Windows 95. If you upgrade to Windows 95, or install the Windows 3.1 printer software after installing Windows 95 the VECPD.386 file is installed. This file prevents the computer from being able to access the printer port properly. To prevent VECPD.386 from loading, remove the following line from the [386 enh] section of SYSTEM.INI and restart your computer:
device=vecpd.386
Article Change History: 27 Feb 1997 - Changed the article title.
Copyright 1995-97, Apple Computer, Inc.
Keywords: kwindows
This information is from the Apple Technical Information Library.
ArticleID: TECHINFO-0019054

Tech Info Library Article Number: 19054

19970227 14:17:48.00