Apple II High-Speed SCSI Card: SCSI Reset Line (11/96)

Article Created: 19 March 1991
Article Reviewed/Updated: 15 November 1996

TOPIC ---

Does the new Apple II High-Speed SCSI Card use the SCSI Reset line as the older
Rev C card? I have a series of hard drives that have the reset line is cut in
the cable and need to know if they will function with the high-speed card, or
will the cable have to be replaced.

DISCUSSION --

The Apple II High-Speed SCSI Card pin assignments are identical to the older
Apple II SCSI Interface card.

The newer card still uses the SCSI Reset Line. You may need to use a special
cable or, in the case of some third-party hard drives, make the appropriate DIP
switch selections.

Article Change History:
15 November 1996 - Reviewed for technical accuracy, revised formatting.

Copyright 1991-96, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19961122 07:37:55.00

Tech Info Library Article Number: 7588