Apple IIGS: Error 911 Is Too Many Sync Errors on ADB

This article last reviewed: 21 July 1989

TOPIC --

On an Apple IIGS with the 0077B ROM installed using GS/OS, I occasionally
run into a Fatal System Error ID=911. In one case, it happens when the
I switch from MS-DOS (Applied Engineering, PC Transporter) to
ProDOS. In another case, it occurs after shutting down the Control Panel.
Running the Cortland Diagnostics does not locate the problem. Error ID=911
has to do with the Apple Desktop Bus.

DISCUSSION --

ID=911 means that too many sync errors occurred on the Desktop Bus. This
problem has been identified but not fixed in currently produced logic
boards. It has, however, been targeted for inclusion in future revisions.
Copyright 1989 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4202