Macintosh Plus P/C: No Response From Apple Personal Modem

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: When using the old MacTerminal program
with the Macintosh Plus and the Apple Personal Modem, there is no
response from the modem.

CAUSE: The Data Terminal Ready (DTR) signal is not activated from
the old serial driver. This signal would normally be used by the
Macintosh to let the modem know that it is activated. Without DTR
the modem will not look at any other signals from the Macintosh.

CURE: Use MacTerminal 2.0 with the new system and finder because
it will activate the DTR signal on the Macintosh Plus.

If the above cure doesn't fix the problem, refer to the Tech
Procedures for this product's troubleshooting procedure.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1884