Tech Info Library

Macintosh IIsi: Math Co-Processor Not On Logic Board

Article Created: 14 June 1991
Article Last Reviewed: 17 July 1992
Article Last Updated:

TOPIC ---

Are the math co-processors on the Macintosh IIsi adapter boards socketed
(and removable) or are they hard-wired?

DISCUSSION --

The co-processors are soldered onto the Macintosh IIsi adapter boards
(this is true of both the Macintosh IIsi 030 Direct Slot Adapter Card and
the Macintosh IIsi NuBus Adapter Card).

The co-processors are not soldered onto the IIsi logic board itself.
Copyright 1991 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8480