# Tech Info Library

## Macintosh IIvx: Radius Video Card and System Crashes (7/93)

Article Created: 21 January 1993
Article Reviewed/Updated: 13 July 1993

TOPIC -------------------------------------------------------------------

Is there a problem with the Macintosh IIvx (Performa 600) and the Radius
Video Card?

DISCUSSION --------------------------------------------------------------

There is a known incompatibility between the installed base of Radius
video cards and the Macintosh IIvx (Performa 600), which may result in system
crashes.

Radius has corrected the problem and has updated all presently shipping
models of their video interface cards and software.  Users who desire to
upgrade their video interface cards to provide IIvx compatibility may
obtain a Software Upgrade Kit by contacting Radius Technical Support.

To locate a vendor's address and phone numbers, use the vendor's name as a
search string.

Article Change History:
07/13/93 - Revised to include Performa 600.
Copyright 1993, Apple Computer, Inc.


Keywords:  KCOMPAT

===================================================================

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number:  11214