HyperCard: Problem Printing to ImageWriter II

This article last reviewed: 25 May 1988

The ImageWriter II has shown a tendency to drop one or two rows of pins
(about 1.5" from the top of the page) only when printing from HyperCard.
This starts on the second page and continues randomly on other pages.
People who experience this also note that other applications print fine.

HyperCard sends a reverse line feed, advances the paper, and tries to
resume printing where it stopped. In doing this, it misses two to three
pixels consistently, about 1.5" from the top of the page. This anomaly has
been reported to the HyperCard Testing group.
Copyright 1988 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2969