MS BASIC Interpreter 2.1: Problem With Macintosh Plus Sound

This article last reviewed: 15 February 1988

The Microsoft BASIC Interpreter version 2.1 has problems with the Macintosh
Plus sound routines. The solution is to upgrade to the Microsoft BASIC
Interpreter version 3.0.
<None>

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2657