Power Macintosh: System Update v 3.0 and Sound In (6/94)

Article Created: 17 Jun 1994

TOPIC --

On Power Macintosh computers, the 'Sound In' option in the Sound Control Panel
determines which sound input source the Macintosh is using. Prior to System
Update 3.0, the setting would always revert back to 'Microphone' after a restart
or shut down.

This is a particular problem for customers playing audio CDs, since the
'Internal CD' and 'Playthrough' settings would have to be re selected after each
restart or shut down.

DISCUSSION --

System Update 3.0 partially addresses this issue. The Sound control panel now
retains the 'Microphone' or 'Internal CD' settings, but still does not retain
the 'AV Connector' settings. If 'AV Connector' is selected as the 'Sound In'
option, the setting will revert to 'Microphone' after a restart or shut down.

If the 'Internal CD' sound setting is not retained after the installation of
System Update 3.0, then the Sound Preferences file is probably corrupted. This
file can be found in the Preferences folder in the System Folder. Throw away the
file and reset the Sound In settings again.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: kppc

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15640