Macintosh II and Control Panel Documents

Article Created: 23 January 1989
Article Last Reviewed: 17 July 1992
Article Last Updated:

Problem: At the top of the Macintosh II screen there are 4 distorted squares
or a row of horizontal dots in the menu bar. These squares show up in any
video mode, but are easier to see on a color monitor if the system is set to
show 16 or 256 colors.

Cause: JClock in the system folder.

Cure: Either remove JClock or replace it with a newer version. The system
files will have to be replaced after JClock is removed or replaced. Use the
Installer program and scripts so the system fonts, Desk Accesories, CDevs and
system inits are not lost.

Problem: Using System software 6.0.2 the Macintosh II freezes when starting
system up.

Cause: Control Panel document - Soundmaster verison 1.0

Cure: Remove the Soundmaster file from System folder or replace it with a
newer version of Soundmaster.

NOTE: Soundmaster and JClock are NOT products of Apple Computer.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3461