Tech Info Library

A/UX 2.0: IBM ftp Problem (8/94)

Article Created: 10 September 1990
Article Reviewed/Updated: 24 August 1994

TOPIC ---

I am having problems with A/UX 2.0 and "ftp". When I do this:

    Account Read

I get the message message:

    230 Working directory is RVFC60 191 (read only)
        Segmentation fault (core dump)

The network components are A/UX on an Ethernet connected to an IBM 8232 gateway
through a Cisco Systems router to an IBM 3090 running IBM TCP/IP. The IBM
operating system being used is VM/XA CMS. The CMS volume referenced in the
error message has a proper READ password and is accessible using the same
technique from a Sun Workstation.

The process worked once, but I'm not sure why. It has failed consistently ever
since. Can you explain?

DISCUSSION ---

We have duplicated the problem you describe, and it will be submitted as a bug
report to A/UX Engineering. One workaround is to enter the "account" command by
itself and then input the account information when "ftp" prompts you for it.
This seems to prevent the core dump and lets "ftp" function normally. This
problem is resolved in A/UX 3.0.

Article Change History:
24 Aug 1994 - Updated for A/UX 3.0

Support Information Services
Copyright 1990-94 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6123