Tech Info Library

800K Disk Eject INIT: Not Available for the Apple IIGS (11/94)

Article Created: 7 August 1990
Article Reviewed/Updated: 21 November 1994

TOPIC --

I use the 800K Eject INIT in Macintosh systems. Is there is a similar program
for the Apple IIGS?

DISCUSSION ---

There is no program for the Apple IIGS that provides the same function as the
800K Eject INIT. There were no reports of drive failures on the Apple IIGS
using 800K disk drives, as there were with some Macintosh systems. Because of
this, such a program is not necessary.

Article Change History:
21 Nov 1994 - Reviewed for technical accuracy.

Support Information Services
Copyright 1990-94, Apple Computer, Inc.

Keywords: hts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5995