Apple IIe and the Numeric Keypad: Some problems

If an Apple IIe is configured with a 342-0132-B ROM as the keyboard ROM, then
the numeric keypad works properly. If there is a 342-0132-C ROM installed, then
the keypad numbers work right but the functions do not. This ROM IS NOT related
to the Mousetext ROM change. A Rev D ROM will be released soon.
Apple Technical Communications

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 883