Print Shop 1.1: Fixes 1MB Apple IIGS Incompatibility

Article Created: 5 March 1991
Article Last Reviewed:
Article Last Updated:

TOPIC ---

I'm using Broderbund's "Print Shop" on an Apple IIGS with 1MB built into
the motherboard. When starting the program, I see a line of hex codes on
the screen, then loading stops. The same disks work fine with the versions
of Apple IIGS with 256K RAM on the motherboard and a 512K memory expansion
card in the slot.

DISCUSSION --

Broderbund has released version 1.1 of their Print Shop software that is
compatible with version 3.0 of the Apple IIGS ROMs. Customers should
contact Broderbund's customer service group for upgrade information.

For more information, search on "Broderbund"
Copyright 1991 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7161