Apple Access II: 'Character Delay' and 'Line Delay'

Access II version 1.1 has fixed the problem of 'Line Delay' working
erratically. In versions previous to 1.1, a line delay of 100 resulted in a
considerable delay, but changing the line delay to 9999 resulted in less
delay.
Apple Technical Communications

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 892