Apple IIGS: AppleTalk must be installed Error

Article Created: 13 August 1991
Article Last Reviewed:
Article Last Updated:

TOPIC ---

I am trying to print AppleWorks on a LaserWriter from an Apple IIGS over
AppleTalk. I downloaded "Apple IIGS: Printing to the LaserWriter from
AppleWorks" from Tech Info on AppleLink. When trying to set this up by
going into the Chooser, I get the error message "Error: AppleTalk must be
installed to run this program."

DISCUSSION ---

The error message is a little misleading. The actual cause is an
improper setting of the slots in the Apple IIGS Control Panel.

With the older Apple IIGS (256K of RAM on the logic board), you need to set
Slot 1 to "Your Card" and Slot 7 to "Built-In AppleTalk". If you have a
newer Apple IIGS (1MB RAM), set only Slot 1 to "AppleTalk". You'll
have to restart after making the changes for them to take effect.
Copyright 1991 Apple Computer, Inc.

Keywords: <None>

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8707