Tech Info Library

Windows 3.x: Printer Driver Prints Incorrectly on LW NTR (3/94)

Article Created: 4 March 1993
Article Reviewed/Updated: 9 March 1994

TOPIC ---

If I use the recommended NT/NTX printer driver in Windows and try to print
envelopes, the software will try to print down the center of the engine (where
envelopes feed on a LaserWriter II). But the NTR feeds envelopes on the side of
the engine, and this doesn't work.

DISCUSSION --

The only suggestion we have is to contact the manufacturer of the driver.
Request that they place in the Page Setup dialog box the flexibility ofselecting
envelope-edge feed or envelope-center feed.

We're sorry but we have no influence on third-party printer drivers written for
the Windows environment.

Article Change History:
9 March 1994 - Reviewed for accuracy

Support Information Services
Copyright 1993-94, Apple Computer, Inc.

Keywords: kwindows

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11785