Tech Info Library

DOS Compatibility Card: LaserWriter Select Print Problem (1/95)

Article Created: 26 January 1995

TOPIC --

I have the DOS Compatibility Card for the Power Macintosh and when I try to
print to the LaserWriter Select 300 from Windows, the Macintosh side freezes. I
have to restart my Macintosh.

DISCUSSION ---

This is a known problem with the LaserWriter Select printer driver and
Background printing. In order to print properly, turn off Background printing
and do not use the QuickDraw GX printer driver.

Support Information Services
Copyright 1995, Apple Computer, Inc

Keywords: kwindows

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17069