ARA and CCL With NOTE Command On Hang Up (9/93)

Article Created: 2 September 1993

TOPIC ---

I have modified a CCL to work with the Defender security system.
Everything works fine until I click the disconnect button. At this point
the Macintosh hangs with "Sorry a system error ... ARA error Type 11". The
entire operating system hangs and the Macintosh must be rebooted.

Now the Macintosh works fine with all other CCL's, and dials up and handles
all Defender Prompts.

1) The customer has a large CCL. The number of branches is not over 128
   but it is large. Could the size of the CCL cause memory errors?

2) Do we know of errors with the disconnect routine?

DISCUSSION ---

We think that when you wrote your CCL you used a NOTE command in the hang
up section of the CCL. The NOTE command is not supported in the hang up
section of the CCL. This is a known problem and has been reported,
although we can't say for sure whether or not it will be fixed in the next
release of ARA.
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13172