Tech Info Library

ARA: Modifying Serial Port B & MacEKG (3/94)

Article Created: 15 March 1994

TOPIC ---

MacEKG shows that ARA is touching, and modifying the node id of serial port B,
even though the modem in the modem port, port A. The node id bounces around
whenever he chooses "answer Calls" in the setup. Why is ARA doing anything to
serial port B?

DISCUSSION --

Micromat Tech Support indicates that they have had similar problem reports
recently. MacEKG should be performing its tests before any other software is
loaded, including ARA.

The workaround is to rename the control panel "•MacEKG" to "   MacEKG™" (three
spaces at the beginning of the name) and to move it from the Control Panels
folder to the Extensions folder. This should ensure that MacEKG is indeed
loading first. Once this is done MacEKG should no longer report that port B is
being "touched", according to Micromat Tech Support.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: <None>

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14971