Tech Info Library

ARA MultiPort Server 2.1 and Serial PCI Card Issue (9/96)

Article Created: 18 September 1996

TOPIC ---

I received Apple Remote Access MultiPort (ARA MP) Server 2.1 with my Workgroup
Server, but I cannot get ARA to recognize the Serial PCI card I purchased
separately for the computer. Why will this not work?

DISCUSSION --

The ARA MP Server v2.1 that ships with the Workgroup Server 7250 and 8550 works
only with the built-in enabler on those computers. Only ARA MP Server v2.1.1
supports PCI cards. There is no upgrade from the bundled version (2.1) of ARA MP
Server to 2.1.1. If you wish to use ARA MP Server with a PCI card, you should
purchase version 2.1.1.

Copyright 1996, Apple Computer, Inc.

Keywords: knts,ksts,kalley

===

This information is from the Apple Technical Information Library.

19960919 11:28:09.00

Tech Info Library Article Number: 20410