FaxSender 1.1: Can't Dial # Symbol (8/93)

Article Created: 8 March 1993
Article Reviewed/Updated: 10 August 1993

TOPIC ---

I'm using Express Modem software and FaxSender 1.1, and I need to dial the #
symbol in the FaxSender application. How can I do this?

DISCUSSION --

Inability to dial # is a bug in FaxSender. It was fixed in the Express Modem
1.0.3 software. The current version of the Express Modem software is 1.0.4.

Article Change History:
10 August 1993 - Problem has been fixed.
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11729