Tech Info Library

Express Modem: Disable Dial Tone Detection (5/95)

Article Created: 11 January 1994
Article Reviewed/Updated: 1 May 1995

TOPIC ---

I am trying to disable the dial tone detection feature on the Express Modem (so that I can call from hotels with non-standard dial tones). In AppleLink, in the Modem string field, I am attempting to put in the Xn codes to disable the dial tone detection. I have tried X0, X1, X2, X3, X4, and none of them have worked.

DISCUSSION --

The Express Modem CCL ignores the Modem String field within AppleLink's Setup Connection.

All changes to AT commands need to be made within the Express Modem CCL itself. The easiest way to edit the Express Modem CCL (assuming it has already been selected via Setup Connection) is to press the Command, Option and E keys while in AppleLink.

To enable blind dialing, X4 needs to be changed to X3 in Label 6.

Article Change History:
01 May 1995 - Corrected typographical error.

Support Information Services
Copyright 1994-95, Apple Computer, Inc.

Keywords: knts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14413