Tech Info Library

Global Village Modems: Smeared Status Bar in PPP Sessions (9/96)

Article Created: 17 September 1996

TOPIC ---

When using FreePPP, the Global Village status bar appears to be multi-colored or
smeared. What is causing this?

DISCUSSION --

According to Global Village, version 2.5.2v2 of FreePPP resolves this issue.

This article provides information about a non-Apple product. Apple Computer,
Inc. is not responsible for its content. Please contact the vendor for
additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you
search for a particular vendor's address and phone number.

Keywords: hts,ksts

===

This information is from the Apple Technical Information Library.

19960918 07:30:18.00

Tech Info Library Article Number: 20401