Network Software Installer 1.3.2: What it Fixes (9/93)

```
Article Created: 1 September 1993

TOPIC -----------------------------------------------------------

This article lists the major changes made to NSI 1.3.2.

DISCUSSION ------------------------------------------------------

Network Software Installer 1.3.2:

• Installs AppleTalk v58.0.2 onto PowerBook Duos.  NSI 1.3 was
  incompatible.
• Recognizes the Centris and Quadra 800 units and installs the latest
  EtherTalk software.  NSI 1.3 didn't install the correct EtherTalk
  software to the Centris and Quadra 800.
• Installs A/ROSE v1.2 which is compatible with the Macintosh IIvx,
  and allows use of the Ethernet NB card on the IIvx system.
• Fixes the compatibility issue between EtherTalk and DecNet tools
  which was broken with NSI 1.3.
• Improves the performance of built-in Ethernet for all 68040-based
  systems.  Anyone using a Quadra should install NSI 1.3.2 for this
  reason.
Copyright 1993, Apple Computer, Inc.


Keywords:  SUPT

==================================================================

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
```

Tech Info Library Article Number: 13167