Tech Info Library

AppleLine: Version 3.35 ROMs Correct Missing 25th Line

This article last reviewed: 2 June 1988

Some AppleLine users have reported that, in MacTerminal, they can't access
the 25th line on the mainframe screen.

The recent ROM revision (version 3.35), which added 3174 support to the
AppleLine, is supposed to automatically bring the AppleLine up in the mode
that displays the 25th line. The old ROMs did not do this: before this
upgrade, the terminal type had to be set to MacTerminal in the AppleLine
Supervisor to display the 25th line.

When AppleLines display the 25th line, either:
- they have the newer ROMs, or
- the AppleLine Supervisor has been set up to display it.
In either case, all AppleLines should have the newest ROMs installed to
ensure compatibility with other possible configurations.
Copyright 1988 Apple Computer, Inc.

Keywords: <None>

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2985