Apple IIc: Splitting the Case

Article Created: 15 July 1986
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Using the normal Take-Apart section for splitting
the Apple IIc case halves is difficult or nearly impossible to perform on some
Apple IIc's that have never been taken apart before.

BEFORE YOU START: Familarize yourself with the Apple IIc Take-Apart
procedure (in Apple IIc Technical Procedures). Also, refer to Macintosh
Technical Procedures to become familar with using the Macintosh Take-
Apart Tool. (Note: Apple IIc Technical Procedures will be revised to reflect
this procedure.)

CURE: The Macintosh Take Apart Tool may be used to split the case halves of
the Apple IIc. Insert the tool between the front case halves and spread them
apart. Once you have the front end split apart try and work your way to the
rear of the computer using the normal splitting procedure (see Apple IIc
Take-Apart).
Copyright 1988, Apple Computer, Inc.

Keywords: hts

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1961