Apple IIe : Double Characters Displayed in 80 Column Mode

Article Created: 22 April 1986
Article Last Reviewed: 17 July 1992
Article Last Updated: 17 July 1992

PROBLEM DESCRIPTION: Apple IIe exhibits double characters in
80 column mode.

CAUSE: Possible bad HAL chip.

CURE: Remove and replace the logic board (HAL not replaceable part) chip
         and test system.

         If the above cure doesn't fix the problem, search on GTS and Apple
         IIe to obtain a general troubleshooting procedure.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1837