Macintosh Displays Single Raster Line

Article Created: 28 October 1986
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: The Macintosh displays a single white
raster line. The line is usually positioned horizontally or
vertically across the screen.

BEFORE YOU START: Familarize yourself with Macintosh Technical
Procedures. ALWAYS DISCHARGE THE CRT TO THE "GROUND LUG". The
Macintosh uses an isolated ground. Performing a discharge to the
chassis will DESTROY the logic board!

CAUSE: In most cases this is an indication of a faulty Power
Supply Board but there exists a possibility that more than one
module is defective.

CURE: Replace the modules in the following order:

1. Replace the power supply and test. If the system is still
   inoperative
   perform Step 2.
2. Replace the Logic Board. If the system is still inoperative
   perform
   Step 3.
3. Replace the CRT. If the system is still inoperative perform
   Step 4.
4. Replace the Power Supply and the Logic board as a set.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2071