Macintosh LC II: LC Ethernet Card Requires New Driver

```
Article Created: 23 March 1992
Article Last Reviewed:
Article Last Updated:

TOPIC ------------------------------------------------------------

I heard that the Macintosh LC Ethernet card works in the Macintosh LC II,
but requires a driver upgrade.

DISCUSSION -------------------------------------------------------

For use in the Macintosh LC II, the Ethernet card requires a ROM upgrade
that contains a new driver.
Copyright 1992, Apple Computer, Inc.


Keywords:  <None>

==================================================================

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
```

Tech Info Library Article Number: 9944