PowerBook 1400: SoftWindows 95 Cannot Read CDs (11/95)

Article Created: 14 November 1996

TOPIC --

I have installed Insignia Solutions SoftWindows '95 on a PowerBook 1400 series
computer. Everything seems to function as expected when I am working in
SoftWindows '95 except that it does not recognize anything in the CD-ROM drive
in the Windows environment.

DISCUSSION --

SoftWindows '95 needs to be upgraded to version 1.0.2 or later in order to
recognize ATAPI interface CD-ROM drives (like the CD-ROM drive in the PowerBook
1400 series computers). A patch to version 1.0.2 can be found on the Insignia
Solutions' ftp site: ftp.insignia.com.

This article provides information about a non-Apple product. Apple Computer,
Inc. is not responsible for its content. Please contact the vendor, Insignia,
for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you
search for a particular vendor's address and phone number.

This article was published in the Information Alley on 14 November 1996.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook,kwindows,supt,ksts,kalley

===

This information is from the Apple Technical Information Library.

19961114 16:00:45.00

Tech Info Library Article Number: 20637