Tech Info Library

PowerBook 500: Sound Manager 3.2.1 Static When Recording (3/97)

Article Created: 3 March 1997
Article Reviewed/Updated: 4 March 1997

TOPIC ---

I have a PowerBook 520 computer, running System Software version 7.5.5. I just
upgraded my QuickTime to version 2.5. Now when I record a sound through the
Sound Control Panel, all that gets recorded is static. It did not do this before
I upgraded to QuickTime 2.5. What is wrong?

DISCUSSION ---

Issue

There is a conflict between non-PowerPC 500 series PowerBook computers and Sound
Manager version 3.2.1, which comes as part of the QuickTime 2.5 installation
package.

Workaround

Remove the Sound Manager 3.2.1 extension from the Extensions folder, restart the
computer, then record the sound.

This issue does not affect PowerBook 500 series computers that have been
upgraded to PowerPC-processors with either Apple's or Newer Technologies'
PowerPC upgrade cards.

This article was published in the Information Alley on 4 March 1997.

Article Change History:
04 Mar 1997 - Added keyword.

Copyright 1997, Apple Computer, Inc.

Keywords: kpbook,kppc,ksts,kalley

==

This information is from the Apple Technical Information Library.

19970305 09:45:40.00

Tech Info Library Article Number: 21048