Tech Info Library

Quadra 950, A/UX 3.0: Serial Switch Setting for System V Spooler

Article Created: 19 February 1993

TOPIC ---

It appears that Quadra 950s running A/UX 3.0 using the System V spooler
(lp) and serial ports have the same problem that the IIfx had running A/UX
2.0 with System V spooler (lp) and serial ports.

DISCUSSION --

Symptoms: Spool some jobs using lp to a serial port on a Quadra 950.
Cancel a spool job. The port locks up (and sometimes the Quadra as well).

Solution: The Quadra 950 needs the Serial Switch (1.1) set to compatible
mode to successfully use the System V spooler.
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11606