Quadra 950 & Digidesign Pro Tools: Use Serial Switch (7/93)

Article Created: 19 July 1993

TOPIC ---

A Macintosh Quadra 950 is giving frequent Type 1 errors when using Pro Tools
from Digidesign. There is a Digidesign Nubus card installed in the Quadra. We
have tried reinstalling the system software, which did not solve the problem.
Is there a problem with the hardware or software from Digidesign?

DISCUSSION ---

When using Pro Tools from Digidesign with a Macintosh IIfx, Quadra 900, or
Quadra 950, you must set the Serial Switch control panel to compatible mode.
This is the case even if the serial ports are not in use at the moment, since
the Pro Tools program attempts to configure the ports as soon as you launch it.
(Other programs may not configure the serial ports immediately, thus the errors
not show up right away. Still other programs won't need Serial Switch set to
compatible mode at all.)

After changing the mode in the Serial Switch control panel, you'll need to
restart your system.

The most recent version of Serial Switch is 1.1.
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12676