Macintosh IIcx: MacIrma 1.2 Compatibility

```
Article Created:  21 June 1989
Article Last Reviewed:  10 July 1992
Article Last Updated:

TOPIC -----------------------------------------

This article discusses Macintosh IIcx and MacIrma version 1.20
compatibility.

DISCUSSION ------------------------------------

According to DCA (Digital Communications Associates, Inc.) support,
version 1.20 or higher of the MacIrma software is required for
compatibility with the Macintosh IIcx.  There appears to be no problem
with the actual fit of the board, itself. Apple has installed one in a
Macintosh IIcx, and there were no problems. Contact DCA concerning upgrade
policy and costs (if any).

To locate a vendor's address and phone numbers, use the vendor name as a
search string.
Copyright 1989 Apple Computer, Inc.


Keywords:  <None>

================================================================

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
```

Tech Info Library Article Number: 4109