AppleShare 1.0, 1.1: Incompatible with AST-4000 3.0

This article last reviewed: 12 October 1987

Version 3.0 of the AST-4000 utilities is incompatible with AppleShare and
can cause server crashes. AST Utilities version 3.2 fixes the problem. Among
other things, it supports changing the SCSI address of the AST-4000. You can
use AST's product BBS (714-660-9175) to download the software and send
queries to the AST's Tech Support group.
Copyright 1989 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 864