Tech Info Library

AppleTalk Phase 2: EtherTalk Driver on Network Product Installer

```
Article Created: 4 March 1992
Article Last Reviewed:
Article Last Updated:


TOPIC -----------------------------------------------------------

What EtherTalk driver is recommended for a Macintosh IIci running system
software version 6.0.7 on an AppleTalk Phase 2 network?


DISCUSSION ------------------------------------------------------

The latest version of the EtherTalk driver is 2.0.1, which is the version
needed for an AppleTalk Phase 2 network.  This driver is available on the
Network Product Installer disk that comes with the version 6.0.7 system
software disks.
Copyright 1992 Apple Computer, Inc.


Keywords:  <None>


==================================================================

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
```

Tech Info Library Article Number: 9897