Tech Info Library

DOS Compatible Card: Open Transport or Classic Network (6/96)

Article Created: 28 March 1996
Article Reviewed/Updated: 21 June 1996

TOPIC ---

After installing the System 7.5 Update 2.0, I am unable to do networking from
the DOS side of my Power Macintosh 6100 DOS Compatible. I have also tried this
on an LC 630 DOS Compatible and a Performa 640 DOS Compatible. None of these are
able to do networking with Open Transport, but they work properly with Classic
networking.

DISCUSSION --

Apple has released version 1.5 of the DOS Compatibility software and strongly
recommends that all owners of previous version of DOS Compatibility cards
(except the Macintosh Centris/Quadra 610 DOS Compatibility Card), upgrade to
this version of software. This software requires an upgrade to Mac OS 7.5.3 with
System 7.5 Update 2.0. With the Power Macintosh 6100, Macintosh LC 630, and
Macintosh Performa 640 DOS Compatibility cards, Classic networking must be
chosen instead of Open Transport.

• If you have a PCI-based computer, you need DOS Compatibility software
  1.5, System 7.5.3, and use Open Transport 1.1. Version 1.5 of the DOS
  Compatibility Software ships with the PC Compatibility Cards.

• If you have a Non-PCI-based computer (for example, a Power Macintosh
  6100 DOS Compatible, LC 630 DOS Compatible, or Performa 640 DOS
  Compatible), you need DOS Compatibility software 1.5, System 7.5.3, and
  use Classic networking by selecting this option in the Network Software
  Selector found in the Apple Extras folder.

Article Change History:
21 Jun 1996 - Complete rewrite of article.
12 Jun 1996 - Added supported computers.

Keywords: supt,kwindows,knts

==

This information is from the Apple Technical Information Library.

19960624 06:53:52.00

Tech Info Library Article Number: 19524