What Is The PowerBook 150 Update Extension? (4/95)

Article Created: 13 April 1995

TOPIC ---

I have a PowerBook 150 which is running System 7.5. Since I installed a modem, the battery seems to get depleted very quickly. What can I do to save battery power?

DISCUSSION --

PowerBook 150 Update Extension

When the PowerBook 150 has an internal modem, the modem continues to draw power when not in use. This shortens the battery life. Apple released the PowerBook 150 Update extension to correct this problem.

The update extends battery life by reducing power requirements during sleep mode. It also fixes a potential system freeze problem that occurs when you use the internal modem several times without restarting the computer.

System 7.5 Update 1.0

If you have installed the System 7.5 Update 1.0, you will no longer need the PowerBook 150 Update extension. The same software fix has been incorporated into the System 7.5 Update file. This file resides "loose" in the System Folder.

The System 7.5 Update file contains the functionality of and removes the following extensions: EM Sound Update, PowerBook 150 Update, and Mount IDE Drive.

Since the PowerBook 150 Update system extension is no longer needed, it is automatically removed from the Extensions folder (inside the System Folder) during installation of the System 7.5 Update 1.0.

These articles can help you locate the software update mentioned here:

• Where To Find Apple Software Updates
  Lists online services for "free" Apple software updates.

• Obtaining Apple Product Support in the USA
  Lists 800 numbers and online services for software updates, Apple

support information, and a subset of the Apple Tech. Info. Library.

Keywords: supt,kpbook,ksts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
Tech Info Library Article Number: 17597