System Software 7.5 Upd 2.0 On My PB 5300/2300/190 (5/96)

Article Created: 13 May 1996

TOPIC --

When I install System Software 7.5 Update 2.0 onto my PowerBook 5300/2300/190
computer, it always skips disk 9, on my earlier PowerBook computers, it skips
disk 12. The install continues fine and runs good, but am I missing something?

DISCUSSION ---

Disk 9 contains only the System 7.5 Update "gibbly" (a term for System Enabler
used in early documentation and system development releases). Since the
PowerBook 5300/2300/190 computers do not have System 7.5, but rather 7.5.2, it
does not need this file and therefore skips it to save space on your hard
drive.

Disk 12 contains the System 7.5.2 Update "gibbly". Since the earlier PowerBook
computers do not have System 7.5.2, it skips this disk.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook,sys75

===

This information is from the Apple Technical Information Library.

19960514 15:31:29.00

Tech Info Library Article Number: 19774