Tech Info Library

System 7: Bus and Address Errors After Clean Install

Article Created: 7 December 1992

TOPIC ---

I still get Bus errors or Finder Address errors even after a clean install.
I have no third-party cards in the computer, and virtual memory and 32-bit
addressing are off. What could be causing this?

DISCUSSION --

The problems could be caused by an improper SCSI configuration. You can
test this by shutting down and disconnecting all external SCSI devices.
Then repeat the clean install on your internal drive with no external SCSI
devices connected. If the problems stop, then troubleshoot your SCSI
chain.

Hint: check for long SCSI cables (5 feet or more), and replace them with
shorter cables.
Copyright 1992, Apple Computer, Inc.

Keywords: SYS7

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10976