System 7.5.3: incompatible with some SuperMac NuBus cards (4/96)

Article Created: 8 April 1996

TOPIC ---

I have a Quadra 950 with a SuperMac NuBus video card, and ever since I updated
to System 7.5 Update 2.0 (System 7.5.3), I can no longer startup in 32-bit mode.
Why?

DISCUSSION --

There seems to be some incompatibilities in some of the older SuperMac NuBus
cards and System 7.5.3. Contact Radius, which owns SuperMac, for information on
workarounds and solutions.

Copyright 1996, Apple Computer, Inc.

Keywords: sys75

19960409 07:56:27.00

Tech Info Library Article Number: 19582