System 7.5 Update 2.0: Removes MacTCP Token Ring Ext. (4/96)

Article Created: 10 April 1996
Article Reviewed/Updated: 18 April 1996

TOPIC ---

I have a Macintosh computer running TCP/IP on a Token Ring network. I recently
installed System 7.5 Update 2.0, but now I am unable to select Token Ring in the
MacTCP control panel. What's going on?

DISCUSSION --

During the installation of System 7.5 Update 2.0, the MacTCP Token Ring
extension is removed. However, the extension is necessary to run TCP/IP protocol
over a Token Ring network from a Nubus-based Macintosh computer. To resolve
this, you'll need to reinstall the MacTCP Token Ring extension. If you do not
have the disks from which you originally got the MacTCP Token Ring extension,
you can download it from the online services.

These articles can help you locate the software update mentioned here:

• "Where To Find Apple Software Updates" - Lists online services for free Apple
software updates.

• "Obtaining Apple Product Support in the USA" - Lists 800 numbers and online
services for software updates, Apple support information, and a subset of the
Apple Tech Info Library.

Article Change History:
18 Apr 1996 - Updated technical information.

Copyright 1996, Apple Computer, Inc.

Keywords: sys75

==

This information is from the Apple Technical Information Library.

19960419 15:09:15.00

Tech Info Library Article Number: 19600