Tech Info Library

System 7.5 Update 2.0: Global Village Startup Error (4/96)

Article Created: 30 April 1996

TOPIC ---

I recently installed System 7.5 Update 2.0 with Open Transport 1.1. Now the
Global Village Toolbox extension will not load at startup because of a memory
error. How can I resolve this?

DISCUSSION --

To prevent this memory error from occuring, you can rename the extension by
putting a space in the beginning of the name. This will force the extension to
load first in the startup sequence and prevent any memory heap issues from
occurring.

Note that you can do this with other extensions as well if they give you similar
errors.

Copyright 1996, Apple Computer, Inc.

Keywords: kcompat,sys75

===

This information is from the Apple Technical Information Library.

19960430 16:39:40.00

Tech Info Library Article Number: 19682