AppleCD 300 Mechanism: Service Shipping Configuration (9/95)

Article Created: 25 May 1993
Article Reviewed/Updated: 7 September 1995

     * RESTRICTED: Apple Internal and Support Providers Only *
                  Not For General Public Release

TOPIC   --

I have a question regarding the shipping configuration of the AppleCD 300
mechanism. Do I ship the service module, 661-1646, AppleCD 300 mechanism back
to Apple Service with or without rails?

DISCUSSION --

The service module for the AppleCD 300 (661-1646) ships without rails.

The AppleCD 300 mechanism, 661-1646, ships for use in different computer
environments. In an environment where the AppleCD 300 mechanism requires rails
(the IIvx/IIvi), Service Providers should remove the rails
prior to shipping the service module back to Apple.

If additional rails are required, the Service part number is 815-0645.

Article Change History:
07 Sep 1995 - Made minor corrections.

Support Information Services
Copyright 1993-95, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12193