AppleVision 1710 Displays: P/N for CRT/Video Board Jumper (7/96)

Article Created: 17 July 1996

```
    * RESTRICTED: Apple Internal and Support Providers Only *
                 Not For General Public Release
```

TOPIC ---

What is the part number for the AppleVision 1710AV and AppleVision 1710 Display
CRT/Video board jumper? The Service Source 2.0, as part of the AppleVision 1710
troubleshooting procedure, explains that I need to replace the CRT/Video board
and install a jumper in connector BV1. However, no part number is provided for
this jumper.

DISCUSSION --

The correct part number for this jumper is 076-0529. This is listed under
diagnostic tools as part of the Extender Cables Kit. This kit includes the
jumper, cables, and adjustment tool.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960718 06:10:40.00

Tech Info Library Article Number: 20177