Disklock 2.1.2: Compatible with 68040 CPUs (10/93)

Article Created: 27 September 1993

     * RESTRICTED: Apple Internal and Support Providers Only *
                   Not For General Public Release

TOPIC ---

If you use DiskLock from Fifth Generation to password-protect drives
and folders, be sure to use version 2.1.2 on 68040 CPUs. Version 2.1
is incompatible with 68040 CPUs with cache turned on.

DISCUSSION --

Fix for the Macintosh:

• Restart a Quadra 840AV using the 840AV Install CD, forcing it to boot
  using Shift-Command-Option-Delete. (The internal drive won't be
  visible.)
• Find Cache Switch, and set for More Compatible.
• Restart again from Install CD. (The internal drive still isn't
  visible.)
• Launch the Emergency Unlock application from the Disklock disk. This
  makes the internal drive visible on the desktop.
• Launch HDSC Setup, and update the drivers on the internal drive.

Fix for DiskLock:

• Download Disklock 2.1.2 Update from AppleLink under Software/Third
  Party.
• Update Disklock 2.1 following instructions.

To locate a vendor's address and phone numbers, use the vendor name as
a search string.
Copyright 1993, Apple Computer, Inc.

Keywords: KSTS

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13449