Tech Info Library

Focus TurboStar: Fix Avaliable for LocalTalk Problem (1/95)

Article Created: 18 January 1995

```
    * RESTRICTED: Apple Internal and Support Providers Only *
                 Not For General Public Release
```

TOPIC ---

A few months ago I was made aware of a problem with LocalTalk performance on a
Power Macintosh 7100. It turned out the customer was using a Focus TurboStar,
which has a LocalTalk chip that doesn't exactly meet the tight specifications of
the Power Macintosh computers. The interim software fix was to install NSI
1.4.3.

The customer has recently upgraded to System 7.5, and reports this fix does not
work. Are there any other workarounds? Or should I recommend that the customer
stick with 7.1.2 until the hardware fix is available?

DISCUSSION ---

Focus Enhancements has a fix available. For more information, please contact:

Focus Enhancements Inc.
800 W. Cummings Park, Ste. 4500
Woburn, MA 01801

617-938-8088
800-538-8865
617-938-7741 (fax)

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: hts,knts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17034