LaserWriter Pro 630: Rev. 2 ROM Description (7/94)

```
Article Created: 14 July 1994

    * RESTRICTED: Apple Internal and Support Providers Only *
                  Not For General Public Release


TOPIC -------------------------------------------------------

How can we tell if we have the new LaserWriter Pro 630 rev.2 ROMs?  Also, what
are the specific changes?


DISCUSSION --------------------------------------------------

The best way to determine if your LaserWriter Pro 630 has the new ROMs is to
check the version number at the top right hand corner of the printer's startup
page.

Here are the specific changes that the LaserWriter Pro 630 v2.0 ROMs include:

1) Revised Courier font improves the visual aspects when printed at 600
   DPI.  Some customers complained that the font appeared lighter on the LW
   Pro 600/630. Customer's who do not have the 2.0 ROM's can download a
   revised Courier font using the LaserWriter Utility.

2) Inserted code patch to minimize network timeout problems. The fix was
   incorporated for a specific customer who experienced problems when using
   the printers on their network. There should be very few instances where
   this code patch is needed.

3) Incorporated EPA Energy Star code.

To summarize, if the LaserWriter Pro 630 has the rev 2.0 ROMs, then you do not
need to download:

- The new Courier font included with the LaserWriter Pro Font Tune-up;  the
  font has been incorporated in the new ROMs.
- The PostScript files included with the LaserWriter Pro Energy Star
  Software to have Energy Star take effect on your LaserWriter Pro 630.  To
  change the "sleep" period for the LaserWriter, you can simply use the
  LaserWriter Utility and select the "Power Saving..." menu item in the
  "Utilities" menu to change it.

Due to the relatively minor changes to the ROMs, there is NO upgrade path for
```

customers. The new ROMs are being rolled into production as well as service
stock for I/O boards.

Keywords: <None>

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
Tech Info Library Article Number: 15822