Tech Info Library

Macintosh II: 32-bit System Enabler (9/95)

Article Created: 27 April 1993
Article Reviewed/Updated: 15 September 1995

        * RESTRICTED: Apple Internal and Support Providers Only *
                     Not For General Public Release

TOPIC ---

This article describes what is needed to use the 32-bit System Enabler with
the Macintosh II.

DISCUSSION --

To use the 32-bit System Enabler, a Macintosh II must have:

• a PMMU
• FDHD (SuperDrive) ROMs
• rev B logic board (required for FDHD ROMs)

Customers can obtain a rev B logic board free of charge, under the warranty
extensions number OMR1020.

This Repair Extension expired on May 3, 1995.

Customers can obtain an FDHD upgrade kit, service part number M6051-C.

This upgrade has been discontinued.

Article Change History:
15 Sep 1995 - Revised to show discontinued upgrade.
24 Feb 1995 - Added new restriction information; reviewed article.

Support Information Services
Copyright 1993-95, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12022